### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

### WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-019791 Address: 333 Burma Road **Date Inspected:** 11-Dec-2010

City: Oakland, CA 94607

OSM Arrival Time: 1900 **Project Name:** SAS Superstructure **OSM Departure Time:** 700 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name:** See below **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No **Delayed / Cancelled:** Yes N/A No

34-0006 **Bridge No: Component:** OBG

### **Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Kelly Leavitt, was present during the times noted above for observations relative to the work being performed.

This QA Inspector observed the following work in progress:

Bay 14

This QA Inspector observed the following work in progress for Bay 14.

ZPMC was using the Flux Core Arc Welding (FCAW) process.

ZPMC QC is identified as Wong Xiang Pin.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specification (WPS).

Listed below are the locations that were identified by this QA Inspector.

Component; 13BW PCMK: DP3133-001

Weld No: 018 Welder: 074866

Weld Repair No: B-CWR2420

WPS-345-FCAW-2G(2F)-ESAB-Repair-FCM

Component; 13CW PCMK: DP3146-001



# WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Weld No: 251 Welder: 202122

Weld Repair No: B-CWR2406

WPS-345-FCAW-2G(2F)-ESAB-Repair-FCM

Component; 13AW, SEG3013A

PCMK: SA3356A Weld No: 002 Welder: 204730 WPS-B-T-2232-ESAB

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

## **Summary of Conversations:**

No significant conversations

### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Leavitt, Kelly	Quality Assurance Inspector
Reviewed By:	Riley,Ken	QA Reviewer